


Assembly instruction TKHP

TKHP 組裝說明書



安全注意事項 / Safety Instructions

請閱讀並遵守以下的組裝說明與注意事項！

Read and follow the assembly instructions and notes!



請按照指示逐步並逐頁進行操作！

Follow the instructions step by step and page by page!

請務必使用適當的搬運工具！

Make sure that you use appropriate means of transportation!



請使用合適的工具！

Use appropriate tools!



注意受傷風險（例如：夾傷等）與必要防護措施

（如：安全帽、護目鏡、工作手套、安全鞋）！

Beware of dangers of injury (e.g. crushing etc.) and apply precautionary Measures (e.g. helmet, protective goggles, working gloves, safety shoes)



在開始對電纜保護鏈條與電纜進行作業前，

請務必先關閉所有電源與機器 / 系統！

Before you start working on the cable carrier and cables, you should generally switch off all energy sources and the machine/ system!



嚴禁觸碰正在運轉的電纜保護鏈條或將物體伸入其中！

It is forbidden to reach into a running energy chain or to hold Objects inside!



禁止進入電纜保護鏈條或其導軌！





Entering the cable carrier or the guiding channel is prohibited!



電力接線必須由合格人員進行！

The electric connection has to be done by a qualified person!


術語對照 / Glossary

	正確 · 動作正確 · 一切正常
	Right, correct movement, all right
	注意 · 請留意
	Attention!, note, recognize
	不正確！錯誤！
	Wrong! Note correct! Error!
	禁止！
	Forbidden! Prohibited!
	平行性
	Parallelism
	相互垂直
	Perpendicular to each other
	重要！
	Important!
	請檢查！
	Control! Check!
	工具與檢具
	Tools and gauges
	非隨附項目
	Not included in the delivery!
	資訊 / 說明
	Information
1 / 2 / 3 abc / (1)	品項編號/ part number
	補充資訊/ additional information's


目次 / Contents

頁數 / Page	主題 / Topic
5	TKHP – 滑動式安裝 / gliding
14	TKHP-R
32	電纜鋪設方式 / Laying the cables


A1




A2



B




C




D




B




B1




B2



B3







C




C1




C2




C3




C4




C5




C6




C7




C8




C9




C10






C17



C18



C19





D



D1

TKHP85



B1-B9 + C15




D2

TKHP90

B1-B9 + C15



D3



Assembly instruction TKHP-R

TKHP-R 組裝說明書



安全注意事項 / Safety Instructions

請閱讀並遵守以下的組裝說明與注意事項！

Read and follow the assembly instructions and notes!



請按照指示逐步並逐頁進行操作！

Follow the instructions step by step and page by page!

請務必使用適當的搬運工具！

Make sure that you use appropriate means of transportation!



請使用合適的工具！

Use appropriate tools!



注意受傷風險（例如：夾傷等）與必要防護措施

（如：安全帽、護目鏡、工作手套、安全鞋）！

Beware of dangers of injury (e.g. crushing etc.) and apply precautionary Measures (e.g. helmet, protective goggles, working gloves, safety shoes)



在開始對電纜保護鏈條與電纜進行作業前，

請務必先關閉所有電源與機器 / 系統！

Before you start working on the cable carrier and cables, you should generally switch off all energy sources and the machine/ system!



嚴禁觸碰正在運轉的電纜保護鏈條或將物體伸入其中！

It is forbidden to reach into a running energy chain or to hold Objects inside!



禁止進入電纜保護鏈條或其導軌！






Entering the cable carrier or the guiding channel is prohibited!






電力接線必須由合格人員進行！

The electric connection has to be done by a qualified person!


術語對照 / Glossary

	正確 · 動作正確 · 一切正常
	Right, correct movement, all right
	注意 · 請留意
	Attention!, note, recognize
	不正確！錯誤！
	Wrong! Note correct! Error!
	禁止！
	Forbidden! Prohibited!
	平行性
	Parallelism
	相互垂直
	Perpendicular to each other
	重要！
	Important!
	請檢查！
	Control! Check!
	工具與檢具
	Tools and gauges
	非隨附項目
	Not included in the delivery!
	資訊 / 說明
	Information
1 / 2 / 3 abc / (1)	品項編號/ part number
	補充資訊/ additional informations


TKHP-R 螺栓鎖緊扭力 / Special torques for TKHP-R




A1




A2




A3




B




C




C1




C2




C3




C4




C5




C6






C7



C8




C9



10 Nm

SW5


C10



Se8




D




Se10




E




F




G




J1




J2




J3




J4




K1




K2




K3




K4




K5




K6



K7




K8




K9




5Nm







T30




K10



K11**K12**

K13**K14**

L



L1




L2




2,5 mm

LineFix


L3




L4




L5







L10




L11




L12




L13




L14




L15




L16




M1




M2




M3




M4



M5



M6



M7

